



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

Jra

May 8, 1980

Docket No. 50-309

Mr. Robert H. Groce
Senior Engineer - Licensing
Maine Yankee Atomic Power Company
25 Research Drive
Westboro, Massachusetts 01581

Dear Mr. Groce:

RE: LOSS OF OFFSITE POWER EVENTS

We are currently reviewing the adequacy of the offsite power systems of nuclear power plants and in particular, the loss of offsite power events at your facility. One aspect of this review concerns the history of experienced total and partial power outages and attendant degraded voltage or frequency conditions of the grid.

In our review of this matter we have drawn upon the information provided to us via Licensee Event Reports and followup letters which have been sent to us. Our records do not indicate that you have experienced any loss of offsite power events either completely or partially. Please review your experiences and, if any are identified, then report them in answer to this letter and furnish the related information as included in the enclosure.

Please provide your response for the Maine Yankee Atomic Power Station within 30 days of the receipt of this letter.

Sincerely,

Robert W. Reid, Chief
Operating Reactors Branch #4
Division of Licensing

Enclosure:
Request for Additional
Information

cc w/enclosure:
See next page

8005221498

Yankee Atomic Electric Company

cc w/enclosure(s):
E. W. Thurlow, President
Maine Yankee Atomic Power Company
Edison Drive
Augusta, Maine 04336

Mr. Donald E. Vandenburg
Vice President - Engineering
Yankee Atomic Electric Company
20 Turnpike Road
Westboro, Massachusetts 01581

John A. Ritsher, Esquire
Ropes & Gray
225 Franklin Street
Boston, Massachusetts 02110

Mr. John H. R. Paterson
Assistant Attorney General
State of Maine
Augusta, Maine 04330

Mr. Nicholas Barth
Executive Director
Sheepscot Valley Conservation
Association, Inc.
P. O. Box 125
Alan, Maine 04535

Wiscasset Public Library Association
High Street
Wiscasset, Maine 04578

Mr. Robert R. Radcliffe
Office of Energy Resources
55 Capitol Street
Augusta, Maine 04330

Robert M. Lazo, Esq., Chairman
Atomic Safety and Licensing Board
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dr. Cadet H. Hand, Jr., Director
Bodega Marine Laboratory
University of California
Bodega Bay, California 94923

Mr. Gustave A. Linenberger
Atomic Safety and Licensing Board
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mrs. L. Patricia Doyle, President
SAFE POWER FOR MAINE
Post Office Box 774
Camden, Maine 04843

First Selectman of Wiscasset
Municipal Building
U. S. Route 1
Wiscasset, Maine 04578

Director, Technical Assessment
Division
Office of Radiation Programs
(AW-459)
U. S. Environmental Protection Agency
Crystal Mall #2
Arlington, Virginia 20460

U. S. Environmental Protection Agency
Region I Office
ATTN: EIS COORDINATOR
JFK Federal Building
Boston, Massachusetts 02203

Stanley R. Tupper, Esq.
Tupper and Bradley
102 Townsend Avenue
Boothbay Harbor, Maine 04538

David Santee Miller, Esq.
213 Morgan Street, N. W.
Washington, D. C. 20001

State Planning Officer
Executive Department
State of Maine
189 State Street
Augusta, Maine 04330

- A. For losses of offsite power where less than all offsite power was lost:*
1. How many circuits to the offsite network are normally available and how many were lost during the event?
 2. What was the cause of the event?
 3. Why did the other lines not fail when some did fail?
 4. Was any voltage increase or decrease experienced just prior to or during the outage? If so, please give details, voltages reached, affects, etc.
 5. Was any frequency decay experienced just prior to or during the outage? If so, please give details, lowest frequency reached, decay rate, affects on equipment operation, etc.
 6. How long was power unavailable from the circuit?
 7. Date of event.
- B. For losses of all offsite power:
1. How long was the power off? How long for partial recovery? Please give details.
 2. If turbine trip occurred, how soon after did loss of offsite power occur?
 3. If power was recovered promptly (10 minutes or less), was it due to automatic or manual actions?
 4. Was any voltage increase or decrease experienced just prior to or during the outage? If so, please give details, voltages reached, affects, etc.
 5. Was any frequency decay experienced just prior to or during the outage? If so, please give details, lowest frequency reached, decay rate, affects on equipment operation, etc.
 6. Date of event.