



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

May 20, 1980

2-050-17

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report No. 80-012/03X-1
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9, attached is the subject report concerning the failure of Diesel Generator #1 which was tripped manually from the Control Room, due to unit load oscillation and vibration during an 18 month surveillance test.

This is an update of a previous report submitted March 13, 1980.

Very truly yours,

David C. Trimble
Manager, Licensing

DCT:GAC:ms

Attachment

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Norman M. Haller, Director
Office of Management and
Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

5 8005280

449

MEMBER MIDDLE SOUTH UTILITIES SYSTEM