STATE OF THE OWNER OWNER

NUCLEAR REGULATORY COMMISSION

REGION I

631 PARK AVENUE KING OF PRUSSIA, PENNSYLVANIA 19406

May 6, 1980

Docket No. 50-213

Connecticut Yankee Atomic Power Company

ATTN: Mr. W. G. Counsil

Vice President - Nuclear Engineering and Operations

P. O. Box 270

Hartford, Connecticut 06101

Gentlemen:

Enclosed is IE Information Notice No. 80-19, "NIOSH Recall of Recirculating-Mode (Closed-Circuit) Self-Contained Breathing Apparatus (Rebreather)," which addresses the NIOSH "stop-sales-and-recall" order to the manufacturers of the BioPak 60P rebreather respirator. Should you have any questions related to the enclosed authorization or guidance, please contact this office.

Sincerely,

Boyce H. Grier

Enclosures:

IE Information Notice No. 80-19

2. List of Recently Issued IE Information Notices

CONTACT: P. Knapp

(215 - 337 - 5291)

cc w/encls:

R. Graves, Plant Superintendent

D. G. Diedrick, Manager of Quality Assurance

J. R. Himmelwright, Licensing Safeguards Engineer

ENCLOSURE 1

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

SSINS: 6870 Accession No.: 8002280674

IE Information No. 80-19 Date: May 6, 1980 Page 1 of 1

NIOSH RECALL OF RECIRCULATING-MODE (CLOSED CIRCUIT) SELF-CONTAINED BREATHING APPARATUS (REBREATHER)

The NRC has been informed by the National Institute for Occupational Safety and Health (NIOSH), the agency that tests and certifies respirators, that some of the NIOSH-certified respiratory protective equipment that NRC licensees use might have been modified by the manufacturer without approval by NIOSH. NIOSH considers such modified equipment not to be certified, even though it might bear their test and certification label.

The equipment in question is the BioPak 30P and 60P, NIOSH test-and-certification numbers TC-13F-84 and TC-13F-85, respectively. The BioPak 30P and 60P are respectively 30-minute and 60-minute, closed-circuit, recirculating-mode, self-contained breathing apparatuses (rebreathers), manufactured by BioMarine Industries, Inc. Our information leads us to believe that NRC licensees have purchased only the 60P equipment.

NIOSH has issued a "stop-sales-and-recall" order to the manufacturer for this equipment. Licensees who have such equipment should check with the manufacturer to determine what action to take to assure that their equipment is in certified status.

The manufacturer's address and telephone number are:

BioMarine Industries Inc. 45 Great Valley Corporate Center Malvern, PA 19355

Tel: (215) 647-7200

ENCLOSURE 2

IE Information Notice No. 80-19 Date: May 6, 1980 Page 1 of 1

RECENTLY ISSUED IE INFORMATION NOTICES

Information Notice No.	Subject	Date Issued	Issued to
80-10	Partial Loss of Non-Nucl Instrument System Power ply During Operation		All Power Reactor Facil- ities with an Operating License (OL) or Construction Permit (CP)
80-11	ieneric Problems With AS Valves in Nuclear Applic tions including Fire Pro tection Systems	:a-	All Power Reactor Facil- ities with an OL or CP, Fue! Fabrication and Processing Facilities
80-12	Instrument Failure Cause Opening of PORV and Bloc Valve		All Fower Reactor Facil- ities with an OL or CP
80-13	General Electric Type SB Control Switches - Defec CAM Followers		All Power Reactor Facil- ities with an OL or CP
80-14	Safety Suggestions from Employees	4/2/80	All Power Reactor Facil- ities with an OL or CP, Fuel Fabrication and Processing Facilities and Materials Priority 1 Licensee
80-15	Axial (Longitudinal) Oriented Cracking in Piping	4/21/80	All Power Reactor Facil- ities with an OL or CP
80-16	Shaft Seal Packing Causes Binding in Main Steam Swing Check and Isolation Valves	5/5/80	All Power Reactor Facil- ities with an OL or CP
80-17	Potential Hazards Associated With Interchangeable Parts On Radiographic Equipmen	5/5/80	All Radiographic Licensees
80-18	Possible Weapons Smuggling Pouch	5/5/80	All Power Reactor Faci- lities with an OL, Fuel Fabrication and Processing Facilities and Materials Priority I Licensees