MORTHEAST UTILITIES



IN HARTLENE FLECTING, MORE COMPANY INSTEAM ANALISECTING, MORE COMPANY INSTEAM ANALISECTING COMPANY INTER WATER POINT R COMPANY INTER AND THE STRUCT COMPANY INTER AND THE STRUCT COMPANY P.O. BOX 270 HARTFORD, CONNECTICUT 06101 (203) 666-6911

May 23, 1980 MP-1-1526

Mr. Boyce H. Grier Director, Region I Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pennsylvania 19406

Reference: Provisional License DPR-21 Docket No. 50-245 Reportable Occurrence R0-79-08/3X-1 (Update Report)

Dear Mr. Grier:

This letter forwards the updated Licensee Event Report for Reportable Occurrence RO-79-08/3L. This update report provides additional information concerning gear casing fracture of the isolation condenser inboard steam supply valve operator. An additional three copies of the report are enclosed.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

John Guk J.F. Opeka

J.F. Opeka Station Superintendent Millstone Nuclear Power Station

JFQ/MJB:kaf

Attachments: LER 79-08/3X-1 and Attachment Update Report

cc: Director, Office of Inspection and Enforcement, Washington, D.C. (30) Director, Office of Management Information and Program Control, Washington, D.C. (3)

8005300410