



Portland General Electric Company

Donald J. Eberle, Assistant Vice President

May 30, 1980

Trojan Nuclear Plant
License NPF-1
Docket 50-344

Mr. R. H. Engelken, Director
U. S. Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 N. California Blvd.
Walnut Creek, CA 94596

Dear Mr. Engelken:

As indicated in my letter of May 19, 1980 confirming my oral report on May 16, 1980 of discovery of a wall which was not adequately connected at its top to interfacing structural elements, and pursuant to Technical Specification 6.9.1.8.1, enclosed is Licensee Event Report 80-77 which describes the condition discovered. A more detailed description and analysis of the occurrence, cause of the occurrence and a description of and basis for the corrective action being taken are provided in the enclosed Reportable Occurrence.

We have determined that this condition was in nonconformance with Technical Specification 5.7.1 in that the wall did not comply with Final Safety Analysis Report requirements. The Plant is currently in Mode 6 with plans to enter Mode 5 approximately June 10, 1980. A schedule for completion of our investigations and modifications is provided in the report.

Sincerely,

Enclosures

c: Mr. Robert A. Clark, Chief
Operating Reactors Branch No. 3
Division of Licensing

Control Building
Service List

Mr. Lynn Frank, Director
State of Oregon
Department of Energy

A002
S
//

8006080411 S