

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | E | M | Y | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 0 | 9 | 7 | 0 | 5 | 0 | 6 | 8 | 0 | 8 | 0 | 6 | 0 | 3 | 8 | 0 | 9  
7 8 9 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During conduct of routine monthly surveillance test procedure #3.1.2, LSI-M-31, the  
0 3 | LPSI Loop 3 header stop valve failed to operate as required. Valve was immediately  
0 4 | placed in the open position till effective repair could be made. Redundant equipment  
0 5 | remained available during the event and there was no effect on public health or  
0 6 | safety.

0 9 | SYSTEM CODE | S | F | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | B | 13 | COMPONENT CODE | V | A | L | V | O | P | 14 | COMP. SUBCODE | A | 15 | VALVE SUBCODE | Z | 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 | LER/RO REPORT NUMBER | 8 | 0 | 21 22 | SEQUENTIAL REPORT NO. | 0 | 1 | 2 | 24 26 | OCCURRENCE CODE | / | 27 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32  
ACTION TAKEN | B | 18 | FUTURE ACTION | E | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 37 40 | ATTACHMENT SUBMITTED | N | 23 | NPRD-4 FORM SUB. | Y | 24 | PRIME COMP. SUPPLIER | A | 25 | COMPONENT MANUFACTURER | L | 2 | 0 | 0 | 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Failure of the valve to open was caused by a broken weld in the coupling of the  
1 1 | operating extension shaft. The coupling was rewelded and the surveillance test  
1 2 | procedure was completed satisfactorily. Motor operator was adjusted to stop on  
1 3 | valve travel limit instead of torque.

1 5 | FACILITY STATUS | E | 28 | % POWER | 0 | 9 | 7 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Routine Surveillance Testing | 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 7 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 8 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

2 0 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45 | NRC USE ONLY  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARER James E. Brinkler

PHONE: 207-882-6321