



CONNECTICUT YANKEE ATOMIC POWER COMPANY

HADDAM NECK PLANT

RR #1, BOX 127E, EAST HAMPTON, CONN. 06424

June 5, 1980

Docket No. 50-213

U. S. Nuclear Regulatory Commission  
Region 1  
Office of Inspection and Enforcement  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Attn: Mr. Boyce Grier,  
Director

Dear Mr. Grier:

This correspondence forwards a Special Report pursuant to Technical Specifications, Section 6.9.3.d, Steam Generator Tube Report. Please be informed that during eddy current testing of Steam Generators #1 and #2, two tubes in Steam Generator #2 exceeded the plugging limit of 50% wall degradation. The defective tubes were Row 40, Column 24 and Row 41, Column 24. Additional inspections were performed in accordance with Technical Specification requirements and no further defects were discovered.

very truly yours,

Richard H. Graves  
Station Superintendent

RHG:JPD/jhb

cc: USNRC, c/o Document Management Branch, Washington, D. C.

*Aug 2 3/0*

*S*  
8006130 270