



MAINE YANKEE ATOMIC POWER COMPANY  
ENGINEERING OFFICE

TURNPIKE ROAD (RT. 9)  
WESTBORO, MASSACHUSETTS 01581  
617-366-9011

June 11, 1980

B.3.2.1  
WMY 80-95

United States Nuclear Regulatory Commission  
Washington, DC 20555

Attention: Office of Nuclear Reactor Regulation  
Division of Licensing  
Mr. Robert A. Clark, Chief  
Operating Reactors Branch #3

References: (a) License No. DPR-36 (Docket No. 50-309)  
(b) USNRC Letter to MYAPC, Amendment No. 48, dated  
March 7, 1980  
(c) MYAPC Letter to USNRC dated June 4, 1980

Subject: Maine Yankee CEA Guide Tube/EOC-4 NP Fuel Inspection Reports

Dear Sir:

Enclosed herewith, please find the following non-proprietary reports, which we agreed to provide under a separate cover letter.

- "End of Cycle 4 Fuel and CEA Eddy Current Inspection Report 1980 Maine Yankee Refueling Outage", CEN-129(M)-NP; and
- "Maine Yankee EOC-4 Summary of Fuel Inspection Results", CEN-131(M)-NP

We trust this information is satisfactory; however, should you have any questions, please do not hesitate to contact us.

Very truly yours,

MAINE YANKEE ATOMIC POWER COMPANY

Robert H. Groce  
Senior Engineer - Licensing

RHG/dis

Enclosures: CEN-129(M)-NP  
CEN-131(M)-NP

THIS DOCUMENT CONTAINS  
POOR QUALITY PAGES

P

8006200 424