

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

June 13, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS - REPORTABLE DEFICIENCY -
DEFECTIVE MCGRAW-EDISON TEMPERATURE DETECTION CONTROLLERS IN THE
STANDBY GAS TREATMENT SYSTEM (SGTS) (NCR'S HNP-A-100 AND PBNP-091)

Initial notification of the subject reportable deficiency was made
to NRC-OIE, Region II, Inspector T. E. Burdette on May 14, 1980.
In compliance with paragraph 50.55(e) of 10 CFR Part 50, we are
enclosing the final report of the subject reportable deficiency.
We consider 10 CFR Part 21 applicable to this reportable deficiency.
If you have any questions regarding this subject, please call
Jim Domer at FTS 857-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stallo, Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
S
1/1

8006200432 S