 NORTHEAST CONSULTANTS, INC.

RD. BOX 550 * DEPOT ROAD * BARRE, MA 01005 * TEL. (508) 355-6626 * FAX (508) 355-6317

October 18, 1989

Docket No. 030-30665
License No. 20-28234-01

Nuclear Regulatory Commission, Region I
475 Allendale Road
King of Prussia, Pennsylvania 19406

Attention: John R. White
Chief Nuclear Materials Safety Section C
Division of Radiation Safety and Safeguards

Subject: Routine Inspection No. 030-30665/89-001

Dear Sir:

This letter summarizes the corrective steps and intent of future actions to be taken in response to a Notice of Violation issued by Mr. Anthony Kirkwood of your office on August 7, 1989

Due to the potential for unauthorized access by employees of our firm, we have since decided to relocate the storage area for the licensed materials to a more secure area of the building. The door for this storage area is double padlocked, and I possess the only set of keys to these locks. There have been no incidents of unauthorized access to the storage area since its completion on September 30, 1989.

Enclosed please find three (3) photographs of the aforementioned area for your files. Based on discussions with Mr. Kirkwood, we have also instituted a policy of typewritten inventory records on a quarterly basis. I personally intend to perform these inspections every three (3) months to insure compliance. I have also submitted a copy of this inventory check for your review. At this time, full compliance has been achieved in accordance with Appendix A of the Notice of Violation.

8911150080 891102
REG1-LIC30
20-28234-01 PDC

Please feel free to contact me if any further information is required.


Sincerely,



Stephen M. Kelly
Radiation Safety Officer
Resource Control, Inc.

SMK/wlt

Enclosure: Three (3) Photographs
Inventory Check Sheet

 NORTHEAST CONSULTANTS, INC.

PO. BOX 550 • DEPOT ROAD • BARRE, MA 01005 • TEL. (508) 355-6826 • FAX (508) 355-6317

September 1, 1989

The intent of this letter is to verify the secure storage of the Troxler Model #3440 Nuclear Density Gauge by the Radiation Safety Officer.

At approximately 9:35 A.M., September 1, 1989, I proceeded to the in-house storage area, located in the Parts Room of Martone Trucking, Inc. Upon arrival, I observed that the exterior door was locked. Visual review of the storage case showed no signs of tampering and this was also locked. I then removed the gauge from the storage case, ensuring that the source rod was in the "Safe" position and the handle was locked. I then resecured the area and terminated my inventory check.

Stephen M. Kelly
Radiation Safety Officer
Northeast Consultants, Inc.

