In Response Refer To: License: 42-23539-01AF

Docket: 30-28641

Department of the Air Force ATTN: Col. David Wood USAF Radioisotope Committee HQ AFOMS/SGPR Brooks AFB, TX 78235-5000

Gentlemen:

Your letter of April 3, 1989, requested review and approval of instrument calibration and radioactive waste procedures for the USAF Occupational and Environmental Health Laboratory (USAFOEHL). At this time we can respond only regarding the calibration procedures. The waste procedure is still being reviewed by NMSS, as are the krypton-85 disposal and thorium-232 licensure questions raised in your letter of April 6, 1989.

In short, we have no objection to the proposed instrument calibration procedures. However, we point out an apparent minor error in the Ludlum Model 61 procedure. On page 3, the (misnumbered) sentence "Calculate...CPM detected/actual CPM" apparently should read "Calculate...CPM detected/actual DPM."

Please note that if the Air Force hires a contractor to perform instrument calibrations at OEHL or elsewhere, the contractor must have a specific license authorizing the calibration of instruments for others.

A. Bill Beach, Director Division of Radiation Safety and Safeguards

bcc:
DMB - Original (IE-07)
RDMartin
ABBeach
LAYandell
BFisher
LShea, RM/ALF (AR-2015)
CLCain
RJEverett
NMIS
MIS System
RIV Files (2)
RSTS Operator

RIV: DRSS WED WLFisher: cd 11/8/89

C:NMOL RJEverett 11/4/89

DD: DRSS LAYande 1/1 11/9/89 D:DRSS ABBeachen

IE-07

8911150222 891109 REG4 11030 42-23539-01AF PDC