

UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

November 9, 1989

Docket Nos. 50-334 and 50-412

MEMORANDUM FOR: John F. Stolz, Director, Project Directorate I-4, Division of Reactor Projects I/II

FROM: Peter S. Tam, Senior Project Manager, Project Directorate I-4, Division of Reactor Projects I/II

SUBJECT: Beaver Vailey 1 and 2 -- Response to Bulletin 88-10 and Supplement 1 to the Bulletin (TAC 71260 and 71261)

By letters dated April 2 and June 19, 1939, the licensee responded to Bulletin 88-10. As a result of Supplement i to the bulletin, the licensee responded by letter dated October 9, 1939 and stated that corrections to its previous responses were not required. The licensee confirmed that activities required to address the issue of substandard molded case circuit breakers discussed in the bulletin and its supplement have all been performed.

The staff has not performed a detailed technical review of the licensee's responses; however, an inspection may be performed at a later date. If a subsequesnt inspection identifies deficiencies in the licensee's actions and responses, this issue will be reopened. Currently, we consider this action complete.

By copy of this memorandum, Region 1 is advised of the licensee's position on this matter.

Peter S. Tam, Senior Project Manager Project Directorate I-4

cc. James C. Stone Ofol Docket files Ilo NRC PDR Ilo Local PDR BV Resident Inspectors