

P137

October 3, 1989

Mr. Wade Green
Institute of Nuclear Power Operations
Suite 1500, 1100 Circle 75 Parkway
Atlanta, Georgia 30339-3064

Dear Mr. Green:

Enclosed for your information is our biweekly listing of generic communications being considered or under development by the NRC staff. These include Bulletins (type coded BL on the list), Information Notices (IN) and Generic Letters (GL). Temporary Instructions, that cover the special NRC inspection effort resulting from certain generic communications, are listed with the type code TI. This listing includes all proposed generic communications that had been reported to us by October 2, 1989.

Sincerely,

Original Signed By
Carl H. Berlinger

Carl H. Berlinger, Chief
Generic Communications Branch
Division of Operational Events Assessment
Office of Nuclear Reactor Regulation

Enclosure:
As stated

DISTRIBUTION w/enclosure:

- ALL NRC Division Directors
- ALL NRC Branch Chiefs
- CERossi, NRR
- CHBerlinger, NRR
- OGCB Members
- JOThoma, NRR
- RFraley, ACRS
- JLieberman, OE
- PDR

Central Files

- DCB
- DOEA R/F
- OGCB R/F
- DKirkpatrick R/F
- SRichardson, DOE
- RBarber, DOE

OGCB:DOEA:NRR
DKirkpatrick
10/2/89 *DKC*

CHB
C/OGCB:DOEA:NRR
CHBerlinger
10/2/89

RD-25
INPO
RF03
11

B910120168 871003
PDR I&E
MISC PDR

NRC FILE CENTER COPY

PROPOSED GENERIC COMMUNICATIONS
IN PREPARATION WITHIN THE NRC

TP ORIGIN. OFFICE	SUBJECT	CONTACT	PHONE	ESTIMATED DATE
IN NRR/DRIS RVIB	ENVIRONMENTAL QUALIFICATION OF LIMITORQUE MOV ACTUATOR TERMINAL BLOCKS & MARATHON 1600 TERMINAL BLOCKS	Steve Alexander	(301) 492-0995	10/31/89
IN NRR/DEST SICB	ERRORS IN CALIBRATION OF LEAD/LAG AND RATE CIRCUITS IN REACTOR PROTECTION SYSTEMS.	Joe Joyce	(301) 492-3265	10/31/89
GL NRR/DEST EMEB	SUPPLEMENT TO GENERIC LETTER 87-11 DEALING WITH ARBITRARY INTERMEDIATE PIPE RUPTURE REQUIREMENTS	Shou-Nien Hou	(301) 492-0904	10/15/89
GL NRR/DEST ESGB	NRR RECOMMENDATION ON ISI OF MARK I & II STEEL CONTAINMENTS, REFUELING CAVITIES & ASSOC DRAINAGE SYS	Chen P. Tan	(301) 492-0829	12/31/89
GL NRR/DEST SELB	RESOLUTION OF GENERIC ISSUE B-56, DIESEL RELIABILITY	Om P. Chopra	(301) 492-0835	02/28/90
GL NRR/DOEA OTSB	LINE ITEM TECHNICAL SPECIFICATION IMPROVEMENT - REMOVAL OF COMPONENT LISTS	Tom Dunning	(301) 492-1189	01/03/90
GL NRR/DEST ESGB	MINIMUM EDGE DISTANCE FOR INSTALLATION OF ANCHORS IN CONCRETE	John Ma	(301) 492-0827	03/31/90
IN AEDD	THE REPORTING OF SAFETY VALVE AND SAFETY-RELIEF VALVE EVENTS PURSUANT TO 10 CFR 50.73	Mary S. Wegner	(301) 492-7818	11/03/89
GL RES/IEB & RPSIB	RESOLUTION OF: GI/70, PORV AND BLOCK VALVE RELIABILITY, AND GI/94, ADDITIONAL LOW TEMP OVERPRESS PROTECTION FOR LWRS	R Kirkwood E Thom	492-3928 -3911	10/16/89
TI NRR/DEST EMEB	INSPECTION OF IMPLEMENTATION OF GENERIC LETTER 89-10: "SAFETY RELATED MOTOR OPERATED VALVE TESTING AND SURVEILLANCE"	Tom Scarborough	(301) 492-0916	11/01/89
TI NRR/DEST SRXB	INSPECTION OF COMPLIANCE WITH BULLETIN 88-04: "SAFETY-RELATED PUMP LOSS"	Mike McCoy	(301) 492-0880	11/30/89

PROPOSED GENERIC COMMUNICATIONS
IN PREPARATION WITHIN THE NRC

TP ORIGIN, OFFICE	SUBJECT	CONTACT	PHONE	ESTIMATED DATE
IN REGION III	FAILURE OF LIMITORQUE VALVE OPERATOR HOUSINGS	John Jacobson	(312) 790-5610	10/17/89
IN NRR/DOEA DGCB	OPERATING EXPERIENCE FEEDBACK	Vernon Hodge	(301) 492-1169	11/03/89
GL NRR/DEST SPLB	CONTROL ROOM HABITABILITY SYSTEMS	Charles Nichols	(301) 492-0854	12/31/89
IN NRR/DOEA DGCB	DIESEL GENERATOR FUEL OIL OXIDATION	Vernon Hodge	(301) 492-1169	11/28/89
GL NRR/DOEA OTSB	LINE-ITEM TECH SPEC IMPROVEMENT - ALT REQUIREMENTS FOR FUEL ASSEMBLIES IN DESIGN FEATURE SECTION OF TECH SPECS	Tom Dunning	(301) 492-1189	10/06/89
GL NRR/DREP PRAB	ACCIDENT MANAGEMENT STRATEGIES FOR CONSIDERATION IN IPE PROCESS - 10 CFR 50.54	R. Palla	(301) 492-1076	10/15/89
BL NRR/DEST ECEB	EVALUATION OF HAZARDS ASSOCIATED WITH HYDROGEN, NITROGEN AND PROPANE USED IN NUCLEAR POWER PLANTS	Frank J. Witt	(301) 492-0823	11/01/89
IN REG V	INGERSOLL-RAND AIR START MOTORS USED ON DIESEL GERERATORS	Don Kirkpatrick	(301) 492-1152	10/03/89
GL NRR/DEST EMTB	GUIDANCE ON TEMPORARY REPAIR OF SERVICE WATER SYSTEM COMPONENTS	Sam Lee	(301) 492-0943	12/31/89
IN NRR/DRIS RSIB	INADEQUATE POST MODIFICATION TESTING	S. V. Athavale	(301) 492-0974	10/03/89
IN NRR/DRIS RSIB	INADEQUATE CONTROL OF TEMPORARY MODIFICATIONS ON SAFETY RELATED SYSTEMS	S. V. Athavale	(301) 492-0974	10/03/89
IN NRR/DEST SELB	GROUNDS IN DIRECT CURRENT DISTRIBUTION SYSTEMS	F. Burrows	(301) 492-0833	10/03/89
IN REGION II	REPOSITIONING OF INTERMEDIATE RANGE NEUTRON DETECTORS CAUSED IMPROPER HIGH-FLUX TRIP SETPOINTS	B. B. Desai	(404) 331-5554	10/03/89

PROPOSED GENERIC COMMUNICATIONS
IN PREPARATION WITHIN THE NRC

TP ORIGIN. OFFICE	SUBJECT	CONTACT	PHONE	ESTIMATED DATE
IN NRR/DREP PRPB	UNEXPECTED HIGH RADIATION AREAS RESULTING FROM SPENT FUEL POOL ACTIVITIES	John Buchanan	(301) 492-1097	10/31/89
IN NRR/DOEA DEAB	DEGRADED GRID VOLTAGE	J. Carter	(301) 492-1194	10/05/89
IN NRR/DREP PRPB	RUPTURE OF DECAYED FUEL ASSEMBLY COULD GIVE EXCESSIVE OCCUPATIONAL SKIN EXPOSURES	Charles Hinson	(301) 492-3148	10/03/89
TI NRR/DEST EMEB	INSPECTION OF IMPLEMENTATION OF GL 89-04: "GUIDANCE ON DEVELOPING ACCEPTABLE INSERVICE TESTING PROGRAMS"	Ted Sullivan	(301) 492-0901	11/01/89
IN REGION II	UNQUALIFIED OPERATORS PERFORMING LICENSED OPERATOR DUTIES IN THE CONTROL ROOM	Jack Ramsey	(301) 492-1167	10/17/89
IN NRR/DOEA DEAB	OVERPRESSURE OF CONTAINMENT SPRAY SYSTEM AND REACTOR WATER SPILL AT MCGRUIRE UNIT 2	Walton Jensen	(301) 492-1190	10/04/89
IN NRR/DEST SRXB	FUEL FAILURE CAUSED BY DRYOUT	Daniel Fiene	(301) 492-3236	10/03/89
IN AEOD/DOA IRB	[NEW] PROPER AND CONSISTENT REPORTING OF SIGNIFICANT EVENTS TO THE NRC	R. J. Strassky	(301) 492-8578	10/18/89
IN AEOD/DSP ROAB	[NEW] FLOW DIVERSION OF SEAL COOLING FOR RHR PUMPS FOLLOWING A LOCA	S. Israel	(301) 492-4437	10/20/89
IN REGION II	[NEW] FAILURE OF LICENSED SENIOR OPERATORS TO CLASSIFY EMERGENCY EVENTS PROPERLY	Charles Casto	(404) 331-4182	10/18/89
IN NRR/DOEA DEAB	[NEW] MCQUIRE 1 STEAM GENERATOR TUBE RUPTURE	Angie Gilbert	(301) 492-1171	10/17/89