

# Victoreen, Inc.

VICTOREEN

U.S. Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Allyn, IL. 60137

April 11, 1989


Subject: 10CFR21 Reportable Data, closure.


Dear Sir:

In accordance with VICTOREEN'S previous report (dated Jan. 27, 1989) the following corrective action has been taken.

Ref:b 3.vii The subject utility was supplied with a new PROM modified to correct the problem with the suspect PROM. A VICTOREEN Field Service Technician installed and tested the new PROM at GPU, TMI. The manual revisions were completed and forwarded to GPU at TMI.

Sincerely,

  
A. Smith, QA Manager

  
K. E. Stafford, Reliability Manager

EGCB/Gullen

SUB - V056

VEN - V056

VEN1 - GPU

Update to \*89-016

Closed VASU/NGTR

5/2/89

8910170208 890418  
PDR PT21 EMVVICT  
89 PNU

6000 Cochran Road  
Cleveland, Ohio 44139-3305  
(216) 248-9300  
FAX (216) 248-9301  
TWX 910 471-8287