



## Department of Nuclear Engineering

Ward Hall  
Manhattan, Kansas 66506 -2503  
913-532-5624

9 Oct 1989

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

Re: Docket 50-188  
License R-88

Gentlemen:

Pursuant to 10CFR50.59(b), the following items are submitted for the Kansas State University TRIGA Mk II Nuclear Reactor Facility for the period 1 Oct 88 through 30 Sep 89.

A. Changes in the Facility: NONE

B. Changes to Procedures:

Revisions to the following procedures were issued on 29 Mar 89 and approved by ballot of the Reactor Safeguards Committee:

Procedure No. 1 - *Biennial Control Rod Inspection* The revision requires (1) inspection and replacement, as necessary, of all electrical and mechanical components within the control rod drive, examination of insulation for deterioration, and examination of movable parts for corrosion, dirt, or deterioration, and (2) examination and replacement, as necessary, of control-rod drive switches at the reactor console.

Procedure No. 9 - *Entrance to the Reactor Bay - Visitor Control*. The revision establishes a new mechanism of accountability for Reactor-Facility keys.

C. Changes to Tests and Experiments: NONE

Sincerely,

Richard E. Faw, Director  
KSU Nuclear Reactor Facility

cc: U.S. N.R.C. (Region IV)  
KSU Reactor Safeguards Committee

8910170272 891009  
FDR ADDCK 05000188  
R FDC

LEA  
1/0