



**PROVIDENCE HOSPITAL**

16001 WEST NINE MILE ROAD  
PO. BOX 2043  
SOUTHFIELD, MICHIGAN 48037  
313 424-3000

D C D / D C B

October 5, 1989

Docket No. 030-02022

License No. 21-02802-03

Roy J. Caniano, Chief  
Nuclear Materials Safety, Section 2  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr. Caniano:

Please find attached our response to the "Notice of Violation," dated September 13, 1989. The attachment describes the actions that have been taken to correct the violations identified in the notice. These corrective actions for Item 1 were effective October 1, 1989, and the corrective actions for Item 2 were effective immediately following the routine safety inspection on August 24, 1989.

These actions have been approved by the facility administration. If there are any questions or need for additional information, please contact me at (313) 424-3043. Thank you.

Sincerely,

Thomas Kasza, Radiological Physicist  
Providence Hospital

cc: Mr. Larry Salwin

enc.1

IE07

OCT 17 1989

Attachment 1.

Response to "Notice of Violation" dated September 13, 1989.

Providence Hospital  
Southfield, MI

Docket No. 030-02022  
License No. 21-02802-03

-----  
The following corrective actions have been taken:

1. Effective October 1, 1989, a daily measurement of the cobalt-57 standard activity is being made using the dose calibrator Tc-99m setting, as well as the Co-57 setting. Tc-99m accounts for over 90-percent of all radiopharmaceutical activity assayed with this dose calibrator.

2. The diagnostic misadministration referred to in this violation was reported using the appropriate USNRC misadministration form and filed in the facility records. There was no record of this report being filed with the NRC office. Effective immediately, we will submit misadministration reports by certified mail, and in accordance with the requirements of 10 CFR Part 35 concerning misadministration reports.

-----