

Nuclear Scanning • Diagnostic X-Ray
672 Fisher Building • Detroit, MI 48202
(313) 871-7633

DCD/DCB

30-18020

END NEW CR

October 10, 1989

NUCLEAR REGULATORY COMMISSION
Roy J. Caniano, Chief
Nuclear Materials Safety
Section 2

RE: LIC. NO. 21-20149-01


Dear Mr. Caniano:

In response to your notice of Violation License Condition 14.A:

- 1) A linearity check will be performed.
- 2) Date for further checks will be posted and signed by the tech and R.S.O. and Medical Consultants, Inc.

This will ensure that the tests are done and can be specifically checked for compliance with license.

Sincerely,


C. Arnold Curry, M.D.

CAC:cc

IE07
OCT 13 1989

8910270094 891010
REG3 LIC30
21-20149-01 PNU



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

SEP 15 1989

New Center Radiology
ATTN: C. Arnold Curry, M.D.
672 Fisher Building
3011 West Grand Boulevard
Detroit, MI 48202

License No. 21-20149-01

Gentlemen:

This refers to the routine safety inspection conducted by J. W. Patterson of this office on August 23, 1989, of activities authorized by NRC Byproduct Material License No. 21-20149-01 and to the discussion of our findings with Raymond Flowers at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.


In addition to the above areas, the inspector examined actions described in your letter dated January 7, 1986, regarding apparent violations found during our October 30, 1985, inspection. We have no further questions regarding these matters.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,


Roy J. Caniano, Chief
Nuclear Materials Safety
Section 2

Enclosure: Notice of Violation

cc w/enclosure:
DCD/DCB (RIDS)

~~8909260267~~ 4p.

Notice Of Violation

New Center Radiology

License No. 21-20149-01

As a result of the inspection conducted on August 23, 1989, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, (1989) (Enforcement Policy) the following violation was identified:

License Condition 14.A requires that licensed material be possessed and used in accordance with statements, representations, and procedures contained in an application dated March 22, 1981.

Item No. 10 of that application requires that the linearity checks for dose calibrators be conducted at the time of installation and quarterly thereafter.

Contrary to the above, from September 27, 1988 to the day of this inspection, August 23, 1989, linearity checks of the dose calibrator had not been conducted at quarterly frequencies. Specifically, during that period, no dose calibrator linearity tests had been done.

This is a Severity Level IV violation (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) the corrective steps that have been taken and the results achieved; (2) the corrective steps that will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

September 15, 1989
Dated

Roy S. Caniano
Roy S. Caniano, Chief
Nuclear Materials Safety
Section 2

8909260316 4p