

DCD/DCB  
30-12554  
21-17319-01

TOXICOLOGY LABORATORY CENTER, INC.

5836 Executive Drive  
Lansing, Michigan 48911  
(517) 882-5791



October 18, 1989

Mr. R. J. Caniano, Chief  
Nuclear Materials Safety  
799 Roosevelt Rd.  
Glen Ellyn, IL 60137

Dear Chief Caniano:

In response to the two violations cited in our recent inspection I wish to state that:

1. Physical inventories will continue to be maintained to account for five nickel-63 foil sources in use at TLC.
2. As previously explained, when a gas chromatograph is running, no wipe tests are performed to minimize or eliminate interference with our daily STA procedures. However, being more aware of the requirements, we will be generating leak-test records for our nickel-63 foil sources. Next routine testing scheduled for January, 1990 and July, 1990 and semi-annually thereafter to be performed by Nuclear Sources Services Inc., Texas.

If you or your staff have any further comment in the above regard, please contact me at your earliest convenience.

Sincerely,

A handwritten signature in black ink, appearing to read 'Gerrit Schut', written in a cursive style.

Gerrit Schut  
Manager

8911010165 891018  
REG3 LIC30  
21-17319-01 PDC

OCT 20 1989

1/0  
IE07