## SAFETY INSPECTION

U.S. NULLEAR REGULATOR	COMMISSI

1. LICENSEE	2	REGIONAL OFFICE	
Robert I. Moretsky & Gerald M. Trager, D.O., P.C.  25600 Schoshnerr Warren, MI 48089		U.S. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT RD. GLEN ELLYN, IL 60137	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE OF INSPECTION	
207.00	21-25922-01	10/25/® 10 <b>23</b>	
030-30607	21-23922-01		
Regulatory Commissions (NRC) rules and representative records, interviews, will 1. Within the scope of this inspection	regulations and the conditions of your th personnel, and observations by the interpretations were observed.	as they relate to radiation safety and to compliance with the Nuclear license. The inspection consisted of selective examinations of procedures spector. The findings as a result of this inspection are as follows:  as identified during the last inspection. We have no further questions on	
3. During this inspection certain of y	our activities, as checked helow, were in		
		was not properly posted to indicate the presence	
B Containers located in		were not properly	
	of radioactive material. 10 CFR 20.20		
		License Condition Number were not properly maintained.	
	posted or otherwise made available. 10 0		
C Beneat or a stiff and an ad			
	Or	License Condition Number	
H			
J			
□ĸ			
		If be taken to correct the violations identified in the items checked above.	
he NRC		of 10 CFR 2.201. No further response will be submitted unless required by	
8911070026 REG3 LIC30 21-25922-0	691025	10	
21-25922-0	1 PDC	1 W/05/89	
SIGNATURE - LICENSE	E DATE	SIGNATURE - NRC INSPECTOR DATE	