In Reply Refer To: License: 35-19048-01 Docket: 30-15283/89-02

Bill Miller, Inc. ATTN: Bill Miller, President P. O. Box 1107 Henryetta, Oklahoma 74437

Gentlemen:

This refers to the special, unannounced radiation safety inspection conducted by Ms. L. Kasner of this office on October 4, 1989, of the activities authorized by NKC Byproduct Material License 35-19048-01, and to the discussion of our findings held by the inspector with members of your staff at the conclusion of the inspection. The enclosed NRC Inspection Report 30-15283/89-02 documents this inspection.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observations by the inspector.

Pleasa note that no violations or deviations were identified.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,

Original Signed By:
A. B. BEACH

A. Bill Beach, Director Division of Radiation Safety and Safeguards

Enclosure: Appendix - NRC Inspection Report 30-15283/89-02

cc: Oklahoma Radiation Control Program Director

RIV: NMISALE LLKasner 10/11/89 C: NMISTRE CLCain 10 /27/89 D DRSS ABBeach

8911080364 891101 REG4 LIC30 35-19048-01 PNU bcc:
DMB - Original (IE-07)
RDMartin
ABBeach
LAYandell
LShea, RM/ALF (AR-2015)
*CLCain
*RJEverett
*LLKasner
*NMIS
*MIS System
*(IV Files (2)
*RSTS Operator
*REHall, URFO
RWise

*W/766