## SAFETY INSPECTION

1. LICENSEE		2 REGIONAL OFFICE	
THE BENDAM GROUP 5314 SOUTH YALE TUISA, OKLAHOMA		United States Muclear Regualatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011	
DOCKET NUMBER(S)	4 LICENSE NUMBERIS	,	B. DATE OF INSPECTION
30-20337	35-23/7/-0	1	OCTOBER 31 1989
Regulatory Commissions (NRC) rules and and representative records, interviews, with and representative records, interviews, with a superior of this inspection.  2. The inspector also verified the steps those actions at this time.  3. During this inspection certain of your THIS IS A NOTICE OF VIOLATIO	regulations and the conditions of you personnel, and observations by the no violations were observed.  You have taken to correct the violatur activities, as checked below, were the which is required to be posted in	tions identified during the lain violation of NRC required accordance with 10 CFR 1	ast inspection. We have no further questions on ements.
TO Deposit of LEAR +FEST	of septen squar	License Con	of sealed sources were not performed at the proposition Number 16
E. Documents were not properly po	of SEAJED SOURCE	10 CFR 19.11.	were not made in accordan
8911170	156 891031		