

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | O | H | D | B | S | 1 | 2 | 0 | 0 | - | 0 | 0 | N | P | F | - | 0 | 3 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

0 1 | L | 6 | 3 | 5 | 0 | - | 0 | 3 | 4 | 6 | 7 | 0 | 4 | 2 | 3 | 7 | 8 | 8 | 0 | 5 | 1 | 8 | 7 | 8 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0015 hours on April 23, 1978, while reviewing the Tagging Log, it was found that  
0 3 | Containment Hydrogen (H2) Dilution Blower 1-1 and the discharge valve of H2 Dilution  
0 4 | Blower 1-2 were both inadvertently tagged out for maintenance. This placed the unit  
0 5 | in the Limiting Condition for Operation (LCO) 3.0.3. There was no danger to the  
0 6 | health and safety of the public or unit personnel. The H2 Dilution System 1-2 could  
0 7 | have been returned to operability if required by re-closing the breaker.  
0 8 | (NP-33-78-51)

0 1 | S | E | 11 | A | 12 | C | 13 | C | K | T | B | R | K | 14 | A | 15 | Z | 16 | 1 | 17 | 7 | 8 | 21 | 22 | 0 | 4 | 1 | 24 | 26 | 0 | 3 | 28 | 29 | L | 30 | 1 | 32 | X | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | 27 | Y | 23 | N | 24 | A | 25 | W | 1 | 2 | 0 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | At 0030 hours on April 23, 1978, H2 Dilution System 1-2 was restored to operability by  
1 1 | removing the tags from the discharge valve of H2 Dilution Blower 1-2. This removed  
1 2 | the unit from LCO 3.0.3. The cause was personnel error; the Maintenance Work Order  
1 3 | on H2 Dilution Blower 1-1 mistakenly listed the circuit breaker of the discharge  
1 4 | valve of H2 Dilution Blower 1-2.

1 5 | E | 28 | 0 | 4 | 6 | 29 | NA | 30 | A | 31 | Found while reviewing Tagging Log | 32 | Z | 33 | Z | 34 | NA | 35 | NA | 36

1 6 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39 | 0 | 0 | 0 | 40 | NA | 41 | Z | 42 | NA | 43 | Z | 44 | NA | 45

8002030057