

MAR 13 1973

W. E. Vetter, Chief, Reactor Construction Branch, RO:III

TOLEDO EDISON COMPANY (DAVIS-BESSE) - DOCKET NO. 50-346
IMPROPER TACK WELDS FOR CLASS 1 PIPING

The licensee submitted a final report of the subject, dated February 12, 1973, in accordance with 10 CFR 50.55(e). The report was prepared by Grinnell Corporation and was dated January 19, 1973. RO's evaluation of this report is contained in the enclosed memo from Potapovs to Henderson dated March 8, 1973. It appears that the nondestructive testing of the affected welds provides reasonable assurance that the welds are sound and acceptable.

RO proposes to audit Grinnell Corporation in the near future to verify that procedures have been implemented to prevent recurrence of this code nonconformance.

Original signed by
J. B. Henderson

J. B. Henderson, Chief
Construction Branch
Directorate of Regulatory
Operations

Enclosure:
As stated

cc:w/encl.
F.E.Kruesi, RO
D.F.Knuth, RO
R.H.Engelken, RO
J.G.Keppler, RO
B.H.Grier, RO:III
Local PDR
PDR
DR Central Files

*50-346
inquiry*

8002030157

bcc:w/encl.
CDR-52 file

OFFICE ▶	RO <i>DEW</i>				
SURNAME ▶	DEWhitesell/ x-7451 mib	JBHenderson			
DATE ▶	3/14/73	3/14/73			