

FEB 6 1973

Toledo Edison Company  
ATTN: G. J. Sampson  
Vice President, Power  
300 Edison Plaza  
Toledo, Ohio 43562

Docket No. 50-346  
Ref. CDR-52

Gentlemen:

Thank you for your report dated January 18, 1973, describing the deficiency identified regarding shop welds of pipe spools for your Davis-Besse facility. We will look forward to receiving copies of the vendor's report of the activities he has implemented to correct this deficiency and to prevent recurrence, as stated in your report.

Your cooperation concerning this matter is appreciated.

Yours truly,

Original signed by  
R. H. Engelken  
**F. E. Kruesi**, Director  
Regulatory Operations

bcc:

L.Rogers, RS  
P.A.Morris, RO  
H.D.Thornburg, RO  
R.H.Engelken, RO  
R.S.Boyd, L  
R.C.DeYoung, L  
F.Schroeder, L  
J.G.Keppler, RO  
G.W.Reinmuth, RO  
A.Schwencer, L

B.H.Grier, RO:III  
M.Steele, RO  
L.Reeder, RO  
DR Central Files  
DR Reading Files  
PDR  
Local PDR  
NSIC  
DTIE, OR

*50-346  
inquiry*

OFFICE ▶	<i>DE</i> DEWhitesell/	<i>JH</i> JBHenderson	<i>RE</i> RHEngelken	<i>FE</i> FEKruesi		
SURNAME ▶	x-7451 mib					
DATE ▶	2/6/73	2/6/73	2/7/73	2/7/73		

8002030169