



UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIVISION OF COMPLIANCE  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

TELEPHONE  
(312) 858-2660

July 20, 1972

J. B. Henderson, Chief, Reactor Construction Branch  
Directorate of Regulatory Operations, Headquarters

TOLEDO EDISON COMPANY  
LICENSE NO. CPPR-80  
DAVIS-BESSE  
ACCIDENTAL DAMAGE TO PUMP VOLUTE NO. 701N0241

The attached report of an inquiry from the subject licensee is transmitted for information. The volute, identified in the attached inquiry report by serial number, is for one of the plant primary coolant pumps.

The licensee was informed that the incident is considered to be fully reportable in keeping with the requirements of 10 CFR Part 50.55(e) and our impression is that the 30-day requirement will be accomplished on schedule.

A handwritten signature in cursive script, reading "W. E. Vetter", is positioned above the typed name.

W. E. Vetter, Chief  
Reactor Construction Branch

Attachment:  
RO Inquiry Rpt No. 050-346/72-01  
(2 cys)

cc: R. B. Monigue, RS (3)  
R. S. Boyd, L (2)  
R. C. DeYoung, L (2)  
D. J. Skovholt, L (3)  
H. R. Denton, L (2)  
G. W. Rinmuth, RO  
H. D. Thornburg, RO  
R. H. Engelken, RO  
RO Files  
DR Central Files

8002030235