

U. S. ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS

REGION III

RO Inquiry Report No. 050-346/72-01

Subject: Toledo Edison Company
License No. CPPR-80
Davis-Besse
Accidental Damage to Pump Volute No. 701N0241

Prepared By: C. M. Erb
C. M. Erb July 18, 1972
(Date)

A. Date and Manner AEC was Informed:

On July 11, 1972, during a routine site inspection, Mr. C. M. Erb was informed of the event as follows:

B. Description of Event:

The pump volute, Serial No. 701N0241 (weighing 12 tons) was shipped from Byron-Jackson, Los Angeles, California, on May 30, 1972, and arrived at the site June 15, 1972. While enroute by C&H Transportation Company, an accident near Tulsa, Oklahoma, caused the volute to roll off the truck.

The inspector examined the volute and found damage to the discharge nozzle and also to the top seal surface where the motor assembly is to be attached. During the inspection, a Toledo Edison QA engineer photographed the damage and gave the inspector a set of three pictures which are on file in the Region III office.

The volute was procured through, and source inspected by, Babcock and Wilcox.

C. Action by Licensee:

Present plans are to ship the volute back to Byron-Jackson for inspection and any required repair.

8002030738