

NRC POSITION REGARDING PLANT ACCESS  
FOR NRC PERSONNEL

NRC PERSONNEL

NRC personnel are visitors to the plant and will generally fall into one of two categories. These categories and the access control procedures for each are described below:

1. NRC personnel who are identified by the Director of the NRC Regional Office as likely to inspect the plant. Such individuals will be provided permanent non-employee, no-escort-required picture badges as authorized by 10 CFR 73.55(d)(5), and added to the authorized personnel list. These badges will be kept at the protected area access control point (gate house) and will be issued to NRC personnel in conjunction with normal identification and search functions.
2. Other NRC personnel. Individuals who fall into category 2 will be treated as normal plant visitors. Plant visits by other NRC personnel will be prearranged. If other NRC personnel, not accompanied by an NRC inspector (category 1), request entry into the plant without prior arrangements, the NRC Regional Office will be consulted immediately.

The NRC Regional Office or other NRC Office, if appropriate, will identify each individual described above with the following information: Name, NRC badge or credential identification number, Social Security Number, date of birth, and clearance (if appropriate). It should be noted that such individuals could include NRC contractors or consultants and in that case, a suitable substitute identification number will be provided.

Individuals falling into category 1 are authorized to serve as escorts for individuals of category 2, consistent with normal plant escort requirements.

8003040 731

F