



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION II  
230 PEACHTREE STREET, N. W. SUITE 218  
ATLANTA, GEORGIA 30305

April 29, 1976

K. V. Seyfrit, Reactor Technical Assistant Branch, Office of Inspection  
and Enforcement, Headquarters

*201* THRU: Norman C. Moseley, Director, Office of Inspection and Enforcement,  
Region II

FLORIDA POWER CORPORATION, CRYSTAL RIVER 3 (DN 50-302), CONTAINMENT DOME  
SEPARATION - REQUEST FOR TRANSFER OF LEAD RESPONSIBILITY

FPC has discovered a separation of the concrete of the containment dome.  
(Morning report April 19, 1976) The utility is currently investigating  
the extent of damage and evaluating methods for repairing the structure.  
Enclosed is a copy of the preliminary notification issued by Region II  
on April 19, 1976, and the preliminary 50.55e report from FPC, dated  
April 21, 1976.

It is requested that lead responsibility for review and acceptance of  
the repair method be transferred to Licensing.

*F. J. Long*

F. J. Long, Chief  
Reactor Operations and Nuclear  
Support Branch

Enclosures:

1. Preliminary Notification
2. FPC letter to NRC dated  
April 21, 1976

cc: F. Jape, IE:II  
C. E. Murphy, IE:II  
H. D. Thornburg, IE:HQ

8003 120 825