

ATOMIC ENERGY COMMISSION

DIRECTORATE OF REGULATORY OPERATIONS
REGION II - SUITE 818
230 PEACHTREE STREET, NORTHWEST
ATLANTA, GEORGIA 30303

TELEPHONE: 14041 828-4803

OCT 9

In Reply Refer To: RO:II:MSK 50-313/73-14

Arkansas Power and Light Company
ATTN: Mr. J. D. Phillips
Vice President and Chief Engineer
Sixth and Pine Streets
Pine Bluff, Arkansas 71601

Gentlemen:

This refers to the inspection conducted by Messrs. W. W. Peery and M. S. Kidd of this office on September 11-14 and 25-28, 1973, of activities authorized by AEC Construction Permit No. CPPR-57 for the Arkansas Nuclear One, Unit 1 facility, and to the discussion of our findings held by Messrs. Peery and Kidd with Mr. J. W. Anderson and other members of your staff at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspectors.

Within the scope of this inspection, no violations were disclosed.

We have also examined actions you have taker with regard to previously identified enforcement matters and unresolved items. The status of these items is identified in Sections II and IV of the summary of the enclosed report.

Three new unresolved items resulted from this inspection and are identified in Section III of the summary of the enclosed report. These items will be examined during subsequent inspections.

In accordance with Section 2.790 of the AEC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclos d inspection report will be placed in the AEC's Public Document Room. If this report contains any information that you believe to be

Should you have any questions concerning this letter, we will be glad to discuss them with you.

specified, the enclosed report and this letter may then be placed in the

Very truly yours,

Norman C. Moseley

Director

Enclosure: RO Inspection Report No. 50-313/73-14

Public Document Room.