

MAY 24 1973

yellow

FS&EB ACTION CONTROL FORM

A. Action Code FO-78
 Name of Licensee and Facility AP & L, Arkansas Nuclear One
 Docket No. or License No. 50-313
 Title Apparent Design Deficiency in Fuel Handling Equipment
 Origin RO:II MR Date Rec'd 5/21/73

B. FS&EB Branch Coordinator:
 Bryan _____ Dreher _____
 Ellis _____ Paulus X _____
 Completion Requested by _____

C. Action Requested of:
 ADREMP _____ M&PPOB _____ EPB _____ RPB _____ ADCO X
 OB _____ CB _____ TAB _____ OOE _____ Region _____
 Date Requested 5/23/73 Completion Requested by 7/20/73
 Reference RO:II Morning Report, 5/21/73

D. Action Requested
 Please review generic aspects of failure in fuel handling equipment.
 Note that AP & L will submit a CDR, presumably before 6/17/73.

E. Date Action Completed _____
 Close-out (Date & Method) _____
 Comments: If completion date is not consistent with your work schedule,
 please let us know.

Harold D. Thornburg
 Harold D. Thornburg, Chief
 Field Support & Enforcement Branch
 Regulatory Operations

8004150735 *Handwritten*