



IE FILE COPY

ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

August 30, 1978

1-088-18

Mr. K. V. Seyfrit, Director
Office of Inspection and Enforcement
Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

Subject: Arkansas Nuclear One - Unit 1
Docket No. 50-313
License No. DPR-51
Reportable Occurrence Report Numbers
50-313/78-20, 50-313/78-21 and 50-313/78-22
(File: 0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 (ANO-1) Technical Specification 6.12.3.2, we have attached the subject reports concerning, 78-20 - the failure of a solenoid valve, SV 7807, supplying control air to VSF-9 discharge damper; 78-21 - RCS leak in the B Reactor Coolant Pump Seal area; and 78-22 - a hydraulic shock suppressor which was not installed correctly.

Very truly yours,

Daniel H. Williams
for Daniel H. Williams
Manager, Licensing

DHW:REI:hh

Attachments

COPY SENT REGION

782490087

8004150780 5

MEMBER MIDDLE SOUTH UTILITIES SYSTEM

A002
1/15 *