

Enclosure (1)

NOTICE OF VIOLATION

Based on the results of the NRC inspection conducted on February 7-10, 1978, it appears that certain of your activities were not conducted in full compliance with conditions of your NRC license DPR-51 as indicated below:

1. Failure to Take Corrective Action for Discrepant Piping

10 CFR 50, Appendix B, Criterion V states in part, "Activities affecting quality . . . shall be accomplished in accordance with these instructions, procedures, or drawings."

The AP&L Quality Assurance Manual Operations, Rev. 4, Section 16, "Corrective Action," paragraph 16.2.1 states, "When deviations, deficiencies, malfunctions, or other abnormal occurrences or conditions are encountered, they shall be reported to responsible authorities for review and disposition in accordance with Section 15 of the Program." Section 15 provides instructions for resolving identified deficiencies and for documenting their resolution

Contrary to the above, the licensee failed to follow the procedures stated above in that nonconformance reports containing disposition and corrective action for the discrepant piping rejected in radiographic test reports 2105, 2110, 2187 and 2113 were neither prepared nor appropriately dispositioned as specified in the Quality Assurance Plan.

This is an infraction.

8004170535