

JAN 22 1975

G. L. Madsen, Chief, Reactor Operations and
Nuclear Support Branch, IE:IV

REQUEST FOR TECHNICAL REVIEW OF REACTOR BUILDING DUCTWORK MODIFICATIONS,
ARKANSAS POWER AND LIGHT COMPANY, UNIT NO. 1 - DOCKET NO. 50-313

The enclosed memorandum from K. R. Collier to B. H. Grier dated January 20, 1976 is a result of our inquiry to the Division of Reactor Licensing (RL) concerning the above subject. (Refer to enclosed memorandum from B. H. Grier to V. A. Moore dated April 29, 1974.) RL has reviewed the Arkansas Power and Light report dealing with the reactor building cool air supply ducts. They have concluded that the corrective action taken by the licensee is adequate and additional review of the ductwork design is not warranted.

Original signed by
K. Seyfrit

Karl V. Seyfrit, Chief
Reactor Technical Assistance Branch

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

800417055.6 5