

E. 8/3/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL

50-313

REC: REID R W
NRC

ORG: WILLIAMS D H
AR PWR & LIGHT

DOCDATE: 07/25/78
DATE RCVD: 08/02/78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED
LTR 1 ENCL 0

SUBJECT:
FURNISHING CORRECTION TO APPLICANT'S LTR 03/31/78 CONSISTING OF RESPONSE TO
NRC FIRE PROTECTION ITEM 4A, RE FIRE PROTECTION VENTILATION FIRE BARRIERS.

PLANT NAME: ARKANSAS -- UNIT 1

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL:

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

FIRE PROTECTION INFORMATION (AFTER ISSUANCE OF OL).
(DISTRIBUTION CODE A006)

FOR ACTION: BR CHIEF ORB#4 BC**LTR ONLY(4)

INTERNAL:	REG FILE**LTR ONLY(1)	NRC PDR**LTR ONLY(1)
	I & E**LTR ONLY(2)	OELD**LTR ONLY(1)
	AUXILIARY SYS BR**LTR ONLY(2)	AD FOR SYS & PROJ**LTR ONLY(1)
	PLANT SYSTEMS BR**LTR ONLY(5)	WAMBACH**LTR ONLY(1)
	R. MURANKA**LTR ONLY(1)	HANAUER**LTR ONLY(1)

EXTERNAL: LPDR'S
RUSSELLVILLE, AR**LTR ONLY(1)
TF.RA**LTR ONLY(1)
NSIC**LTR ONLY(1)
ACRS CAT B**LTR ONLY(16)

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

DISTRIBUTION: LTR 39 ENCL 0
SIZE: 1P

CONTROL NBR: ~~72-218800~~
MA *[Signature]*

***** THE END *****

8004230654

[Handwritten mark]



REGULATORY DOCKET FILE COPY

ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

July 25, 1978

1-078-17

Director of Nuclear Reactor Regulation
ATTN: Mr. R. W. Reid, Chief
Operating Reactor Branch #2
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: Arkansas Nuclear One-Unit 1
Docket No. 50-313
License No. DPR-51
Fire Protection Ventilation
Fire Barriers
(File: 1510, 2040)

Gentlemen:

Our letter of March 31, 1978, on the above subject transmitted our response to your fire protection Item 4a. However, recent plant inspections have indicated that part of that response (which was based on information provided by our architect-engineer) is in error as we have discovered several ventilation ducts penetrating fire barriers without a 3-hour fire damper. We will install dampers (by the end of the next refueling outage) such that all ventilation ducts penetrating fire barriers will have dampers in accordance with the above referenced response.

We apologize for this inadvertent situation and will make every effort to correct it as soon as possible.

Very truly yours,

Daniel H. Williams
Manager, Licensing

DHW/JTE/ew

~~78-150100~~

A006
5/10