

Reactor Facility Branch

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76012

March 10, 1976

Arkansas Power and Light Company
ATTN: Mr. J. D. Phillips
Senior Vice President
Sixth & Pine Streets
Pine Bluff, Arkansas 71601

Docket No. 50-313

Gentlemen:

Thank you for your letter of March 1, 1976 in response to our letter and Notice of Violation, dated December 23, 1975. As a result of our review of your letter and discussions with Mr. Cavanaugh of your staff on March 8, 1976, we request that you provide additional information for Infraction 1.B. Specifically, your response does not indicate that documentation is available as evidence that the preoperational baseline inservice inspection program was conducted. Secondly, your response does not address the need for a change to procedure QCP 1004.03 which would clearly allow inspections to be conducted, on your behalf, by subcontractors or vendors.

It is requested that the additional information specified above be submitted to this office within 20 days of your receipt of this letter.

Should you have questions concerning this request, we will be pleased to discuss them with you.

Sincerely,

G. L. Madsen
G. L. Madsen, Chief,
Reactor Operations and
Nuclear Support Branch

bcc w/ltr W. Cavanaugh to G. L. Madsen, dtd 3/1/76

IE Chief, FC&EB
IE Chief, APD
IE Chief, TAB
IE Region IV Coord.
IE Files

Central Files
Standards Development
DRL (12)
TIC
NSIC

PDR:HQ
Local PDR
Ark State Board of Nuc Energy

8004230

709