



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

JUN 9 1977

Docket No. 50-329  
Docket No. 50-330

Consumers Power Company  
ATTN: Mr. Stephen H. Howell  
Vice President  
1945 West Parnall Road  
Jackson, MI 49201

THIS DOCUMENT CONTAINS  
POOR QUALITY PAGES

Gentlemen:

This refers to the special inspection conducted by Messrs. D. W. Hayes of this office and R. E. Shewmaker of IE Headquarters, Washington, D.C. on May 4, 1977, of activities at the Midland Nuclear Power Plant construction site authorized by NRC Construction Permits No. CPPR-81 and No. CPPR-82. A discussion of the findings from the site inspection was held with Messrs. G. L. Slagel and D. R. Keating of your staff.

The enclosed copy of our inspection report addresses the subject concerning the misplaced and omitted hoop tendon sheaths in the Unit 1 containment building below the main steam line penetrations and the status of the preparation of the Unit 2 containment liner plate bulge area for repair. Within the scope of these subjects, the inspection consisted of an examination of specific records and engineering drawings, observations and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room, except as follows. If the report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from

8006090 601

Q

40

JUN 9 1977

public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

R. F. Heishman, Chief  
Reactor Construction and  
Engineering Support Branch

Enclosure: IE Inspection  
Report No. 50-329/77-04  
and No. 50-330/77-07

cc w/encl:  
Mr. Mike Sewell, Nuclear  
Licensing Administrator  
Central Files  
Reproduction Unit NRC 20b  
PDR  
Local PDR  
NSIC  
TIC  
Ronald Callen, Michigan Public  
Service Commission  
Dr. Wayne E. North  
Myron M. Cherry, Chicago

OFFICE →	RIII <i>Heishman</i>	RIII <i>Heishman</i>	IE:HO <i>Shewmaker</i>			
SURNAME →	<i>Heishman</i>	<i>Heishman</i>	<i>Shewmaker</i>			
DATE →	6/7/77	6/8				