PDR



UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

NUL 1 7 1980,

Docket No. 50-346

Toledo Edison Company ATTN: Mr. Richard P. Crouse Vice President

Nuclear Edison Plaza 300 Madison Avenue Toledo, OH 43652

Gentlemen:

This refers to the investigation conducted by Messrs. C. H. Weil and T. J. Madeda of this office on June 5 and 6, 1980, of activities at the Davis-Besse Nuclear Power Station, Unit 1, authorized by NRC Operating License No. NPF-3, and to the discussions of our findings with Mr. Terry Murray, Station Superintendent and Mr. Michael Polk, Corporate Security Manager, at the conclusion of the investigation.

The enclosed copy of our investigation report (Enclosure 2) identifies areas examined during the investigation. Within these areas, the investigation consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this investigation certain of your activities appeared to be in non-compliance with NRC requirements, as described in the enclosed Appendix A (Enclosure 1). The investigation showed that action had begun to correct Item 1, which should prevent recurrence. Consequently, no reply to this item is required. However, you are requested to provide a written response to the remaining items.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

Several areas examined during this investigation (Enclosure 3) concern subject matter which is exempt from disclosure according to Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Consequently, Enclosures 1 and 3 to this letter and your response

to the noncompliance identified in those enclosures will not be placed in the Public Document Room. Therefore, your statement of corrective action regarding the noncompliance identified in Enclosure 1 should be submitted as a separate enclosure to your transmittal letter.

We will gladly discuss any questions you have concerning this investigation.

Sincerely,

James G. Keppler Director

Enclosures:

- Appendix A, Notice of Violation (Part 2.790(d) Information)
- IE Investigation Report No. 50-346/80-18
- Appendix B, Report Details
 of Noncompliance (Part 2.790(d)
 Information)

cc w/encls:

T. D. Murray, Station Superintendent Central Files Reproduction Unit NRC 20b

cc w/encl 2: PDR Local PDR