

APPENDIX A

NOTICE OF VIOLATION

Tennessee Valley Authority
Browns Ferry

License Nos. DPR-33 and DPR-52

Based on the NRC inspection April 5 through May 2, 1980, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

- A. As required by Item 6.3.A.1 of the facility technical specification, detailed written procedures, including checkoff lists, shall be prepared, approved and adhered to for surveillance and testing requirements.

Contrary to the above, on April 22, 1980, Surveillance Instruction 4.1.A-7, Reactor Protection System Reactor Water Level, was not adhered to during its performance on Unit 2 in that system alignment was not followed.

This is an infraction which is applicable to Unit 2.

- B. As required by 10 CFR 50.72(a)(7), the licensee shall notify the NRC Operations Center as soon as possible and in all cases within one hour by telephone of the occurrence of significant events which are listed. Item (7) on the list requires reporting of events resulting in manual or automatic actuation of Engineered Safety Features, including the Reactor Protection System.

Contrary to the above, a prompt report was not made to the NRC Operations Center following the automatic actuation of the "B" Diesel Generator at 1:00 p.m. on April 23, 1980.

This is an infraction which is applicable to Units 1 and 2.