



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION II  
101 MARIETTA ST., N.W., SUITE 3100  
ATLANTA, GEORGIA 30303

TTC

JUL 15 1980

In Reply Refer To:  
RII: PAT  
50-321  
50-366

Georgia Power Company  
Attn: J. H. Miller, Jr.  
Executive Vice President  
270 Peachtree Street  
Atlanta, GA 30303

Gentlemen:

This refers to the meeting conducted at your request in the Region II office on June 27, 1980. This meeting related to activities authorized by NRC license numbers DPR-57 and NPF-5 and was attended by members of the Region II staff and R. J. Kelly and members of your company.

The subjects discussed at this meeting are described in the enclosed meeting summary.

It is our opinion that this meeting was beneficial and has provided for a better understanding of inspection and enforcement issues. In accordance with section 2.790 of NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and enclosures will be placed in the NRC's Public Document Room.

Should you have any questions concerning this matter, we will be pleased to discuss them.

Sincerely,

*R. C. Lewis*  
R. C. Lewis, Acting Chief  
Reactor Operations and Nuclear  
Support Branch

- Enclosures:  
1. Meeting Summary  
2. Attendance List

cc's w/encls:  
M. Manry, Plant Manager  
C. E. Belflower, Site  
QA Supervisor  
W. A. Widner, Vice President  
and General Manager

Enclosure 1

MEETING SUMMARY

Licensee: Georgia Power Company

Facility: Hatch 1 and 2

License Nos.: DPR-57 and NPF-5

Docket Nos.: 50-321 and 50-366

Subject: High Pressure Coolant Injection (HPCI) and Reactor  
Core Isolation Coolant (RCIC) System Malfunction

On June 27, 1980, representatives of Georgia Power Company met with NRC Region II personnel in Atlanta, Georgia. The purpose of the meeting was to discuss with the licensee their schedule and planned corrective actions regarding the failure of the HPCI and RCIC systems to perform as designed following a reactor trip on Hatch 1, on June 26, 1980.

The licensee gave a presentation which outlined programs for determining the cause for system failures, the review of plant practices and activities which may affect system performance and a comprehensive test program to ensure that HPCI and RCIC systems perform as designed. An NRC representative acknowledged Georgia Power Company's presentation and emphasized the need to closely review for adequacy the surveillance procedures, the test requirements and personnel technical training as they apply to the HPCI and RCIC systems.

It was noted that a followup meeting would be held in Region II office to discuss the results of the licensee investigations and retest programs.

*C. Julian for*  
\_\_\_\_\_  
P. A. Taylor

*7/15/80*  
\_\_\_\_\_  
Date Signed

Enclosure 2

ATTENDANCE LIST

Attendance at the GPC-NRC meeting on June 27, 1980, at the Region II Office.

Office of Inspection and Enforcement, Region II

James P. O'Reilly, Director  
F. J. Long, Deputy Director  
R. C. Lewis, Acting Chief, Reactor Operations and Nuclear Support Branch  
C. A. Julian, Reactor Inspector  
P. O. Taylor, Reactor Inspector

Georgia Power Company

R. J. Kelly, Vice President, Power Generation  
W. A. Widner, Vice President and General Manager, Nuclear Generation  
J. T. Beckman, Manager of Nuclear Generation