

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

JUN 2 7 1980

Docket No. 50-346

Toledo Edison Company ATTN: Mr. Richard P. Crouse Vice President Nuclear Edison Plaza 300 Madison Avenue Toledo, OH 43652

Gentlemen:

This refers to the inspection conducted by Messrs. L. Hueter and L. Reyes of our office on April 21-24, and May 2 and 6-8, 1980 at the Davis-Besse facility. This inspection covered the radiation protection program during refueling and the circumstances surrounding the excessive radiation exposure received by an employee. The report setting forth the results of the inspection is enclosed.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information.

A separate letter setting forth certain matters of concern and the items of noncompliance found during this inspection has been sent from the Director, Office of Inspection and Enforcement. Your response to those items should be made directly to that office.

8008010031

Toledo Edison Company

4

- 2 -

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Gen W. Roy GJames G. Keppler Director

Enclosure: IE Inspection Report No. 50-346/80-12

cc w/encl: Mr. T. D. Murray, Station Superintendent Central Files Reproduction Unit NRC 20b PDR Local PDR NSIC TIC Harold W. Kohn, Power Siting Commission Helen W. Evans, State of Ohio