



MAINE YANKEE ATOMIC POWER COMPANY •  
ENGINEERING OFFICE

TURNPIKE ROAD (RT. 9)  
WESTBORO, MASSACHUSETTS 01581  
617-366-9011

B.4.1.1

WMY 80-105

July 7, 1980

United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Attention: Mr. Boyce H. Grier, Director

References: (a) License No. DPR-36 (Docket No. 50-309)  
(b) USNRC Letter to MYAPC dated May 6, 1980;  
IE Bulletin No. 80-10

Subject: Response to IE Bulletin No. 80-10, "Contamination of Non-Radioactive System and Resulting Potential for Unmonitored, Uncontrolled Release to Environment"

Dear Sir:

Your letter, Reference (b), identified a contamination event at another facility and requested that Maine Yankee document completion of the actions required in items 1 and 2. Maine Yankee has completed a design and operation review to (1) identify systems that are considered non-radioactive but could become contaminated through interface with radioactive systems; and (2) established a sampling program to promptly identify any contaminating events which could lead to unmonitored, uncontrolled releases to the environment.

We trust this information is satisfactory; however, should you require additional information, please contact us.

Very truly yours,

MAINE YANKEE ATOMIC POWER COMPANY

D. E. Moody  
Manager of Operations

RHG/ncj

8008010204

Q