

APPENDIX A

NOTICE OF VIOLATION

The Griffin Hospital
Derby, Connecticut 06418
License No. 06-13905-01

Docket No. 030-01300

Based on the results of an NRC inspection conducted on March 10, 1980, it appears that certain of your activities were not conducted in full compliance with NRC regulations and the conditions of your license as indicated below:

- A. 10 CFR 19.12 requires that you instruct all individuals working in your restricted areas in the applicable provisions of the Commission's regulations and licenses.

Contrary to this requirement, on the day of the inspection, March 10, 1980, individuals who were working in your restricted area had not been instructed in the applicable provisions of the regulations and the conditions of your license. Specifically, your technical staff had not been instructed in your requirement for checking the dose calibrator and surveying the hot laboratory on a daily basis.

This is an infraction.

- B. Condition 17 of your license requires that licensed material be possessed and used in accordance with the statements, representations and procedures contained in your application dated October 7, 1970 and a letter received February 23, 1976.

1. Item 4.f. of your letter received February 23, 1976, requires that all personnel who prepare, dispense and administer radiopharmaceuticals will monitor hands and clothing for contamination after performing these tasks.

Contrary to this requirement, on March 10, 1980, an individual working in your hot laboratory failed to monitor hands and clothing after performing these tasks. This individual was noted to have easily detectable levels of radioactive contamination on his hands.

2. Item 11 of this letter requires that your dose calibrator response be checked at the beginning of each day with a Cs-137 source.

Contrary to this requirement, as of March 10, 1980, you had not checked the response of your dose calibrator with a Cs-137 source since August 8, 1979.

8008060 039

3. Item 10 of this letter requires that your Nuclear Medicine "hot lab" be surveyed at the end of each working day.

Contrary to this requirement, as of March 10, 1980, you had failed to make the required surveys since August 7, 1979.

These items are infractions.

- C. Condition 12 of License No. 06-13905-01 limits the use, or supervision of use, of licensed material for diagnostic purposes to a named physician.

Contrary to this requirement, as of March 10, 1980, byproduct materials authorized by your license have been used during the periodic absence of the named physician.

This is an infraction.

- D. 10 CFR 35.14(e) requires that sealed calibration or reference sources possessed pursuant to 10 CFR 35.14(d) be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to this requirement, as of the day of the inspection, March 10, 1980, you have failed to leak test your sealed cesium-137 reference source at the appropriate intervals.

This is an infraction.