



Huntington

TESTING & TECHNOLOGY INC.

P. O. Box 1618
Huntington, West Virginia 25717
Telephone (304) 453-6111
Fax (304) 453-3576

October 9, 1989

Nuclear Regulatory Commission,
Attention: Document Control Desk
Washington, DC 20555

Subject: Reply to a Notice of Violation

Gentlemen:

This letter is in response to the Notice of Violation dated September 22, 1989, Docket #030-20243, resulting from Inspection Report #47-22076-01/89-01. The following is Huntington Testing's response to the individual violations:

Violation A - Huntington Testing agrees the violation is accurate and correct. It is our opinion that this violation occurred due to the significant and rapid growth of the company without the re-organization of management and supervision keeping pace with the growth. Within the last 90 days, the company management has been restructured to ensure that no individual has more job responsibilities that can be effectively accomplished. These measures had already been executed at the time of Mr. Franklin's Inspection and we are now, and will continue to be, in full compliance. To better achieve prompt film badge exchanges, the attached memo has also been forwarded to each radiographer.

Violation B - Huntington Testing agrees the violation is accurate and correct. It is our opinion that the violation was a result of the conditions outlined in Violation A, with the same corrective action taken. Essentially, the individual responsible for the Radiation Safety Program no longer has any operational responsibilities, thereby allowing more attention to be focused on safety and training. We feel that full compliance has been reached.

Violation C - Huntington Testing agrees the violation is accurate and correct. This violation occurred due to major renovations to the present facility. The Co60 source which caused the violation was being temporarily stored in a locked room adjacent to a hallway, an abandoned restroom and a locked ladies restroom. To reduce the radiation levels to an acceptable level on the exterior of this room, shielding has been placed around the projector. As soon as the current renovations are completed, 30-60 days, a permanent and proper storage area will be constructed.

8910170281 891009
NMSS LIC30
47-22076-01 PDC

IE07
1/0



Nuclear Regulatory Commission

Page - 2 -

The Management of Huntington Testing has a longstanding dedication to its Radiation Safety responsibilities. The items of violation found in the recent audit are not in keeping with normal company policies. Proper action for the correction of these items has been initiated and greater attention will be given to the program as a whole.

Sincerely,

HUNTINGTON TESTING & TECHNOLOGY, INC.

William G. Yeoman,
President & General Manager



DATE: September 13, 1989
TO: ALL TECHNICIANS
FROM: Clyde W. May

A recent NRC Inspection has revealed discrepancies in film badge exchange policies:

ALL film badges are to be exchanged on the fifth (5th) of each month without exception. If you are working on an out-of-town jobsite, film badges are to be returned to this office within three working days after the exchange date. Arrangements will be made for exchanges through overnight mail if necessary. Failure to comply with this policy could result in withholding of payroll checks.