

OCT 11 1989

Docket No. 50-186

University of Missouri
ATTN: Dr. J. Steven Morris
Director, Research
Reactor Facility
Research Park
Columbia, MO 65201

Gentlemen:

This refers to the routine inspection conducted by Mr. J. P. Patterson of this office on September 26-28, 1989, of activities at the University of Missouri Research Reactor Facility, authorized by Operating License No. R-103 and to the discussion of our findings with you and others of your staff at the conclusion of the inspection.


The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas the inspection consisted of a selective examination of procedures and representatives records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,


L. Robert Greger, Chief
Reactor Programs Branch

8910180046 891011
PDR ADOCK 05000186
Q PDC

Enclosure: Inspection Report
No. 50-186/89002(DRSS)

cc w/enclosure:
DCD/DCB (RIDS)
Licensing Fee Management Branch
R. Erickson, EPB, NRR

RIII
TP
Patterson/jh
YES

RIII
TP
Snell
YES

RIII
Pederson
YES

RIII
Greger

IEOK