

OCT 11 1989

In Reply Refer To:
License: 20-26933-01
Docket: 30-30466/89-01

Raytheon Service Company
ATTN: William C. Head
Program Manager, ATC
2 Wayside Road
Burlington, Massachusetts 01803

Gentlemen:

Enclosed for your records is NRC Form 591, "Safety Inspection." Please note that no violations were observed by Mr. Wesley L. Holley during the September 11, 1989, initial inspection of your NRC Byproduct Material License 20-26933-01. No response to this letter is necessary.

During the inspection, the NRC inspector discussed with Mr. W. Patrick Fedoronic: (1) the safety aspects of your licensed activities and compliance with regulatory requirements, (2) the NRC and DOT requirements, (3) the licensee's commitments made during the licensing process, and (4) the NRC enforcement policy.

If you have any questions concerning this matter, please call me at (817) 860-8100.

Sincerely,

Original Signed By:
CHARLES L. CAIN

Charles L. Cain, Chief
Nuclear Materials Inspection Section

Enclosure:
NRC Form 591

cc:
Colorado Radiation Control Program Director

bcc:

✓ DMB - IE-07
RDMartin
ABBeach
WLFisher
LShea, RM/ALF (AR-2015)

*CLCain
*WLHolley
*MIS System
*RIV Files (2)
*RSTS Operator (Close Report.)
*NMIS

*w/766

RIV:NMIS *W* C:NMIS *W*
WLHolley/ch CLCain
9/12/89 10/9/89

8910180234 891011
REG4 LIC30
20-26933-01 PDC

IE-07