

DCD/DCB

03030701

**Ball-InCon**  
**Glass Packaging Corp.**  
1509 South Macedonia Avenue  
Muncie, IN 47302-3664  
(317) 741-7000

Reply to: P.O. Box 4200  
Muncie, IN 47307-4200

October 2, 1989



U. S. Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Attn: D. J. Sreniawski, Chief  
Nuclear Materials Safety, Section 1

Re: **License No. 13-25942-01**  
Ball-InCon Glass Packaging Corp.  
Okmulgee, OK Plant

Dear Mr. Sreniawski,

In reference to your letter of September 22, 1989, concerning the above license, the question of a record of physical inventory of the source has been resolved. Mr. Walter King of your office, who initiated the telephone contact, had asked about the physical inventory inspection and recordkeeping required by License Condition 15. I told Mr. King that this information would be kept at the Okmulgee, Oklahoma facility, and I could not confirm during our phone conversation.


Action has been taken to address the physical inventory question. Mr. Fred Exter, Okmulgee plant Radiation Safety Officer, has been contacted and confirms that the source in question is present in its proper location. The required periodic inventories have been performed but the records were apparently misplaced. Mr. Exter has instituted a formal inspection procedure to insure that the necessary records are maintained following future inventories. Also, copies of required inspections and tests will be retained in the Muncie, Indiana, office in the event of a future telephone contact.

8910250252 891002  
REG3 LIC30  
13-25942-01 PNU

1 E 07  
OCT 10 1989

I trust that this will satisfy your request. Please contact me at (317) 741-7145 if there are any further questions.

Sincerely,

  
Marvin C. Gridley  
Project Engineer

cc: Mr. Fred Exter - Okmulgee