

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-295

As a result of the inspection conducted on September 25 through October 5, 1989, and in accordance with the "General Policy and Procedures for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1989), the following violation was identified.

Technical Specification 3.7.2.c requires that with the TDAFW pumps inoperable, two operable flow paths shall be established from the MDAFW pumps to all steam generators within eight hours.

Contrary to the above, Unit 1 operated at power in the run mode from 6:40 p.m. on July 23, 1989, to 11:48 a.m. on July 24, 1989, which exceeds the time allotted by Technical Specification by nine hours and eight minutes, without establishing two operable flow paths from the MDAFW pumps to the steam generators.

This is a Severity Level IV violation (Supplement 1). 295/89033-01(DRP)

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement of explanation in reply, including for each violation: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

10-17-89

Dated

W.D. Shafer

W. D. Shafer, Chief
Reactor Projects Branch 1