

APPENDIX A

NOTICE OF VIOLATION

Northeast Nuclear Energy Company
Milistone Unit 3

Docket No. 50-423
License No. DPR-65

During a routine resident inspection from July 18 through August 28, 1989, the following violation was identified in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C:

10 CFR 50.73 (a)(2)(vii)(C) requires the holder of an operating license for a nuclear power plant to submit within thirty days a Licensee Event Report (LER) for any event that occurs which causes two independent trains or channels to become inoperable in a single system designed to control the release of radioactive material.

Contrary to the above, on May 24, 1989, while fuel movement was in progress in the fuel building, a security guard opened a roll-up door in the fuel building which effectively rendered the two fuel building independent ventilation trains inoperable.

As of August 28, 1989, the licensee had not submitted an LER for the event.

This is a Severity Level IV Violation (Supplement I).

Pursuant to 10 CFR 2.201, Northeast Nuclear Energy Company is hereby required to submit to this office, within thirty days of the date of the letter which transmits this Notice, a written statement or explanation in reply including: (1) the corrective steps taken and results achieved; (2) corrective steps to be taken to avoid further violations; (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.