DCS No: 3003754881109 Date: November 9, 1988

## PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE--PNO-I-88-117

This preliminary natification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region I staff on this date.

Facility: Combustion Engineering, Inc. Windsor, Connecticut	Licensee Emergency Classification:  Notification of Unusual Event Alert
License No. 06-00217-06 Docket No. 30-03754	Site Area Emergency General Emergency X Not Applicable

Subject: RECEIPT OF CONTAMINATED PACKAGE

On November 9, 1988, the licensee reported to NRC Region I that a contamination survey of a box of equipment received on November 7 resulted in a single contamination measurement of 50,000 dpm/100 cm2. No other wipes revealed any abnormal contamination levels. The box was shipped in an exclusive-use vehicle from a reactor facility, Arkansas Nuclear One, Russelville, Arkansas. The box arrived with the lid loosely in place and with no evidence that the box had been banded prior to shipment. The initial radiation survey by the licensee on November 7 indicated a maximum radiation level of 10 millirem per hour (mrem/hr) on the surface of the box and no removable contamination. The surveys performed at the reactor facility, which were recorded and sent to the licensee with the shipment, indicated a maximum radiation level of 960 mrem/hr at the surface of the box and no removable contamination. The elevated contamination levels were measured by the licensee on November 9 during additional surveys to identify possible "hot particles". The licensee is investigating to determine whether the measured removable contamination represents loose contamination or a single "hot particle". No c., tamination was found by the licensee in the vehicle after the shipment was unloaded. Region IV has been informed and will review the actions of the reactor facility with regard to the shipment. The licensee reported the incident in accordance with 10 CFR 20.205(b)(2), which requires the reporting of removable contamination on packages in excess of 22,000 dpm/100cm2. The State of Connecticut has been informed.

Region I will continue to monitor the licensee's actions. This information is current as of  $4:00\ p.m.$ , November 9, 1988.

CONTA	\C1.	346-5275		346-5252		346-5251				
DISTR	IBUT	ION:								
OWFN			MNBB		H-St		NL	Mail:	ADM: DMB	
Chair Comm.		Zech erts	AEOD		H-St ACRS PDR		RES		DOT: Trans	only
000	Cari	r	OGC					NRC Op	s Ctr	
CLOS.	Poge	ers								
Comi	Cur	tiss					INPO			
SECY		MSS					NSAC			.,
CA	N	RR								IE341
OGC	0	IA	Regio	onal Offic	es					101
GPA	0:						RI Reside	nt Offi	ce	
PA	SI	LITP								
EDO	OF						Licensee:			
	891	1020243	38110	9				(React	or Licenses	25)
	PNO-	18E -1-88-11	7 P	DC						