



Southern California Edison Company

23 PARKER STREET
IRVINE, CALIFORNIA 92718

November 13, 1989

F. R. NANDY
MANAGER OF NUCLEAR LICENSING

TELEPHONE
(714) 587-5400

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Docket No. 50-206
Report of NPDES Permit Violation
San Onofre Nuclear Generating Station, Unit 1

Pursuant to Section 6.16.2.c of Appendix A, Technical Specifications, to Provisional Operating License No. DPR-13 for San Onofre Unit 1, enclosed is a copy of the September 1989 monthly NPDES report summary for Unit 1. The report summary includes a description of a violation of the NPDES permit. There were no violations at either Unit 2 or Unit 3 during September.

If you require any additional information, please so advise.

Sincerely,

Enclosure

cc: J. B. Martin (Regional Administrator, USNRC Region V)
C. W. Caldwell (USNRC Senior Resident Inspector, Units 1, 2, and 3)

8911210164 891113
PDR ADOCK 05000206
S FDC

IEL3
11

Southern California Edison Company



SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

October 27, 1989

Mr. Ladin Delaney, Executive Officer
California Regional Water Quality Control Board
San Diego Region
9771 Clairemont Mesa Boulevard, Suite B
San Diego, California 92124-1331

Dear Mr. Delaney:

Subject: NPDES Monitoring Report
San Onofre Nuclear Generating Station, Unit 1

The SONGS monitoring report covering the month of September is submitted in accordance with the requirements of CRWQCB Order 88-001 (NPDES Permit No. CA0001228). A summary of the generating unit's status and significant analytical results is provided below.

The unit was operational during September. All sampled water sources were found to be within permit limits, except the Mesa Sewage Treatment Plant effluent which was high on settleable solids September first due to hydraulic overload. This was due to the unanticipated early shutdown of one of the units for refueling and the associated influx of contractors awaiting badge processing. The situation was solved by starting up train "B" and increasing the amount of treatment plant in use.

Pursuant to Order No. 88-001, Reporting Requirement 12, the following representative is authorized to sign and certify all reports required by this order: Arthur Kneisel, Environmental Engineer.

I certify under penalty of law that I have personally examined and am familiar with the information submitted in the attached document, and based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

Sincerely,

B. Katz
Manager, Site Support Services

Enclosure

cc: Environmental Protection Agency, Region IX